


? 43/ ??????? ?3

 C 821 (1,17 з)	 C 822 (6,78 з) ф1.25 - 32шт, ф1.5 - 16шт, ф5.0 - 6шт	 C 823 (2,1 з) ф1.0 - 14шт	 C 824 (4,39 з) ф1.5-6шт Мз6х3-4шт Гр5х3-4шт
 C 825 (4,89 з) ф1.75 - 40шт	 C 826 (3,45 з) ф1-22шт ф3.75-2шт	 C 827 (2,08 з)	 C 828 (4,66 з) ф1.75-48шт
 C 829 (4,35 з) Гр 4х3 - 2шт, Кв 2х2 - 18шт	 C 830 (5,53 з) ф2.0 - 8шт, ф3.0 - 6шт	 C 831 (8,16 з) ф3.0 - 34шт	 C 832 (6,2 з) ф3.25-4шт Гр7х5-6шт
 C 833 (4,85 з) Гр 4х3 - 2шт ф1.75 - 50шт	 C 834 (4,89 з) ф1-50шт ф1.5-4шт ф2-2шт	 C 835 (8,51 з) ф1.75-12шт ф3.5-2шт Ов6х4-12шт	 C 836 (5,16 з) Мз 8х4-2шт Мз 6х3-4шт Ф1.75-2шт Ф1.5-2шт Ф1.25-2шт
 C 837 (7,47 з) ф1.5 - 24шт ф4.0 - 12шт	 C 838 (4,63 з) ф1.0 - 24шт Шар12 - 2шт	 C 839 (3,83 з) ф1.0 - 24шт	 C 840 (2,29 з) ф1.75-16шт

C-43



??????.

??????? : ??? ???? ???????
????
????

[?????? ?????? ?? ????? ??????](#)

???????

???????

?????? 3.

?????.