




?-56/ ??????? ?5

 3.0rp KE-1035 Ф3.0-3шт Ф1.5-2шт Ф1.25-10шт Ф1.0-80шт	 4.5rp KE-1036 Ф4.0-1шт Ф2.0-6шт Ф1.5-6шт	 4.6rp KE-1037 Ф1.0-76шт	 3.5rp KE-1038 Ф6.0-1шт Ф1.25-16шт
 3.3rp KE-1039 Ф8.0-1шт Ф1.25-38шт	 5.2rp KE-1040 Ф8.0-1шт Ф1.25-20шт	 3.1rp KE-1041 Об6.0x4.0-1шт Ф1.25-16шт	 4.9rp KE-1042 Ф1.25-30шт
 3.4rp KE-1043 Ф4.0-1шт Ф1.25-21шт	 10.4rp KE-1044 Ф1.5-111шт Ф1.25-15шт	 3.4rp KE-1045 Ф8.0-1шт Ф2.0-16шт	 3.4rp KE-1046 Сч7.0-1шт Ф1.75-12шт Ф1.5-12шт Ф1.25-12шт
 3.1rp KE-1047 Ф7.0-1шт М34.0x2.0-8шт	 3.1rp KE-1048 Ф6.0-1шт Ф1.25-16шт	 3.6rp KE-1049 Ф6.0-1шт Ф1.5-24шт	 3.0rp KE-1050 Ф7.0-1шт Ф2.0-8шт
 4.2rp KE-1051 Ф6.0-1шт Ф1.25-10шт	 7.8rp KE-1052 Об 9.0x7.0-1шт Ф1.25-32шт	 2.9rp KE-1053 Ф6.0-1шт Ф1.25-34шт	 13.8rp KE-1054 Ф1.25-310шт

K-56



??????.

??????? : ??? ????
???
???

[?????? ?????? ?? ????? ??????](#)

??????
???????.
?????? 5.
?????.